



SandCat Overhead Controller — I/O Wiring · SYNC INPUTS (Scale 1–2, Drop Sync 1–6)

Sensor power from the +24/–24 bus (right). Signal: field device ► TB-1 ► OPTO input. OPTO COM = –24.



Sensor power from the +24/-24 bus (right). Signal: field device ▶ TB-1 ▶ OPTO input. OPTO COM = -24.



SandCat Overhead Controller — I/O Wiring · DROP (KICKER) OUTPUTS 1–24

OPTO output V+ from the +24 bus. Out ► TB-1 ► kicker solenoid coil; solenoid return to –24. (RED OPTO output module.)

