



Reliability Laboratory

## TEST REPORT

Report No.: HC80119/2022

Page: 1 of 9

Date: September 7, 2022

ELGENS CO., LTD.

7F-6., NO.492, BANNAN RD.,

ZHONGHE DIST., NEW TAIPEI CITY, TAIWAN

The following merchandise was submitted and identified by the vendor as:

Product Description: Panel PC  
Style/ Item No.: LPC-P156W-2VET7/ No.1  
Manufacturer/Vendor: Elgens Co., Ltd.  
Country of Origin: Taiwan  
Quantity: Total 1 set  
Testing Period: Aug. 17, 2022 to Aug. 25, 2022

We have tested the submitted sample(s) as requested and the following results were obtained:

Test Required: (According to client's test specification, please see following sheets in detail.)

1. Functional Vibration Test
2. Long-Life Vibration Test
3. Operating Mechanical Shock Test

Test Results: - PLEASE SEE ATTACHED SHEETS -

Signed for and on behalf of  
SGS TAIWAN Ltd.

Alex Chen  
Asst. Supervisor

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明，此報告結果僅對測試之樣品負責，同時此樣品僅保留 90 天。本報告未經本公司書面許可，不可部份複製。  
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at [www.sgs.com.tw/Terms-and-Conditions](http://www.sgs.com.tw/Terms-and-Conditions) and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at [www.sgs.com/en/terms-and-conditions/terms-e-document](http://www.sgs.com/en/terms-and-conditions/terms-e-document). Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

## TEST REPORT

Report No.: HC80119/2022

Page: 2 of 9

## 1. Functional Vibration Test:

Test Equipment:

| Name                  | Brand          | Model              | Serial No. |
|-----------------------|----------------|--------------------|------------|
| Vibration Tester      | UNHOLTZ-DICKIE | SAI60-H560BAC/2/ST | 474        |
| Controller            | Dactron        | LASER              | 7110357    |
| Control Accelerometer | PCB            | 353B34             | LW213529   |

Lab Environmental Conditions:Ambient temperature:  $(25 \pm 3) ^\circ\text{C}$ Ambient humidity:  $(55 \pm 20) \% \text{RH}$ Test Location:No.31, Wu Chyuan Road, New Taipei Industrial Park, WuKu District,  
New Taipei City, Taiwan.Test Method/ Specification:Test method: EN 50155: 2021 Clause 13.4.10.4, Functional random vibration test and client's requestSample condition: OperatingWave form: RandomFrequency: (5 ~ 150) Hz

| Longitudinal axis                          |                                 | Transverse axis                            |                                 | Vertical axis                              |                                 |
|--------------------------------------------|---------------------------------|--------------------------------------------|---------------------------------|--------------------------------------------|---------------------------------|
| Frequency (Hz)                             | ASD ( $\text{m}^2/\text{s}^3$ ) | Frequency (Hz)                             | ASD ( $\text{m}^2/\text{s}^3$ ) | Frequency (Hz)                             | ASD ( $\text{m}^2/\text{s}^3$ ) |
| 5                                          | 0.015163                        | 5                                          | 0.0062663                       | 5                                          | 0.0315667                       |
| 20                                         | 0.015163                        | 20                                         | 0.0062663                       | 20                                         | 0.0315667                       |
| 150                                        | 0.000273307                     | 150                                        | 0.000112948                     | 150                                        | 0.000568977                     |
| ⇨ equivalent to 0.70 ( $\text{m/s}^2$ )rms |                                 | ⇨ equivalent to 0.45 ( $\text{m/s}^2$ )rms |                                 | ⇨ equivalent to 1.01 ( $\text{m/s}^2$ )rms |                                 |

Direction: Longitudinal, Transverse, Vertical direction (See photo 3 ~ 5)Duration: 30 minutes/ axis

- Examine the appearance of specimen(s) by visual check and perform functional check after this test.
- Functional check: Turn on the power of specimen(s) then examine whether the booting function of specimen(s) could be work normally or not.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明，此報告結果僅對測試之樣品負責，同時此樣品僅保留 90 天。本報告未經本公司書面許可，不可部份複製。

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at [www.sgs.com.tw/Terms-and-Conditions](http://www.sgs.com.tw/Terms-and-Conditions) and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at [www.sgs.com/en/terms-and-conditions/terms-e-document](http://www.sgs.com/en/terms-and-conditions/terms-e-document). Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.