

Tindakan Perbaikan yang disarankan/Suggested corrective actions	
<p>Potong Rock bolt dengan gunoda</p>	

		LAPORAN BAHAYA	
Nama Pelapor/Reporter Name	INN. Ref No./INN Event No.		
KETUT			
Tanggal : 3.1.2026	Waktu : 10.50		
Dept. Penanggung Jawab/Responsible Dept.	Pengawas Area/Supervisor Area		
UG Mironing	Herdi S?		
Lokasi / Location	RL 120 Acc		
Rincian Bahaya/Hazard details			
<p>Rock bolt menonjol di lantai area Ctr 300</p>			
Tindakan Perbaikan Langsung/Immediate corrective actions			
<p>melaporkan ke perwira area</p>			

LAPORAN BAHAYA

Penilaian Risiko/Risk Assessment
(Dilisi oleh pengawas/Completed by Supervisor)



Kemungkinan/Probability :	E-2	Tingkat Risiko / Risk Rank :	R
Konsekuensi/Consequence:	E-2		

Tindakan perbaikan yang dilakukan/Corrective Actions Suggested

Mengelap bolak-balik
menanggul ke sec

Komentar/Comments

Bolu bolu sudah di potong.

Diselesaikan oleh/Close out Report by

Tanda Tangan Pengawas/
Supervisor's Signature : Hendri S

Tanggal/ Date : 31.12.6

No. Form: TT-OHS-FOS-60-038A HAZID