Pin-out

USB: 5 V out as powered by the USB connection 3V : regulated 3.3 V out, max. 500 mA peak GND: ground

A0 : analog out, 0 to 3.3 V : ref_X*
A1 : analog in , 0 to 3.3 V : sig_I

12 : digital trigger out : trig out

For testing connect A0 to A1, i.e. directly feed ref X* into sig I.

