USB: 5 V out as powered by the USB connection 3V : regulated 3.3 V out, max. 500 mA peak

GND: ground
A0 : analog out, 0 to 3.3 V: ref_X*

A1 : analog in , 0 to 3.3 V: sig_I
12 : digital trigger out : trig_out

For testing connect A0 to A1, i.e. directly feed ref X* into sig I.

