



(a)



(b)

Figure 3.2: Calculation of fitting parameters: (a) f_1 and f_2 from output curve ($V_{GS} = V_{DD}$) (b) f_3 and f_4 from transfer curve ($V_{DS} = 0 \ldots V_{DD}$ *with* $0.1V$ *step-size*).