



Opening the Electronics Enclosure






2 Grab your trusty 4mm wrench from the back of the tool




Remove the button head screw from the left, top side of the clear electronics enclosure.




4 Slide the electronics enclosure to the left.



5 Pull the electronics enclosure away from the tool.




6 You now have access to the FabMo Control Card and Interface Board of your Handibot.




If you need to access the power supply of your Handibot, start by removing the six screws on the back and side of the rear wall using your 4mm wrench



8 Continue by removing the two screws holding the bottom of the rear wall in place.



9 Pull back on the top of the rear wall to expose the power supply.



You now have access to the power supply for your Handibot.

