
Figure 48 — SHAP Feature Importance for Relay Decisions
Sensor quality
PV generation level
PS (norm.)
Own trip time (norm.)
CTI slack (norm.)
Topology change flag
CTI violation flag
PS (norm.) [dup]
Fault current (norm.)
TMS (norm.)
0.00
0.02
0.04
0.06
0.08
0.10
0.12
0.14
0.16
Mean |SHAP Value|