
Figure 24 — Sensor Robustness: Performance Under Measurement Degradation
Gaussian Noise
Relative Performance
0.41
0.40
0.39
0.38
0.00
0.05
0.10
0.15
0.20
Noise Level (sigma)
Systematic Bias
Relative Performance
0.44
0.43
0.42
0.41
0.40
0.00
0.02
0.04
0.06
0.08
0.10
Bias Level
Missing Measurements
Relative Performance
0.418
0.416
0.414
0.412
0.410
0.00
0.05
0.10
0.15
0.20
Missing Rate