


GEORGE_BATCHVAROV

Main Level

Main Level

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
1. Equipment setup, take down, and monitoring (hourly charge)	3.00 HR	0.00	50.58	0.00	151.74
3. Protect - Cover with plastic	300.00 SF	0.00	0.26	1.80	79.80
4. Haul debris - per pickup truck load including dump fees	1.00 EA	130.66	0.00	0.00	130.66
Total: Main Level				1.80	362.20



Kitchen

535.33 SF Walls
290.01 SF Ceiling
825.34 SF Walls & Ceiling
290.01 SF Floor
32.22 SY Flooring
66.92 LF Ceil. Perimeter

Height: 8'

Missing Wall

9' 11" X 8"**Opens into LIVING ROOM**

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
7. Remove Laminate - simulated wood flooring - High grade	100.00 SF	0.94	0.00	0.00	94.00
9. R&R Baseboard - 2 1/4"	10.00 LF	0.34	2.48	0.46	28.66
11. R&R Base shoe	10.00 LF	0.14	1.21	0.25	13.75
12. Clean floor	290.01 SF	0.00	0.37	0.00	107.30
14. Dehumidifier (per 24 hour period) - No monitoring	1.00 EA	0.00	51.32	0.00	51.32
15. Negative air fan/Air scrubber (24 hr period) - No monit.	10.00 DA	0.00	71.29	0.00	712.90
16. Apply anti-microbial agent to the floor	290.01 SF	0.00	0.24	0.70	70.30
17. Contents - move out then reset	1.00 EA	0.00	45.70	0.00	45.70
19. Remove 1/2" - drywall per LF - up to 2' tall	10.00 LF	1.80	0.00	0.00	18.00


Totals: Kitchen

1.41

Height: 8'

Laundry


237.33 SF Walls
46.85 SF Ceiling
284.18 SF Walls & Ceiling
46.85 SF Floor
5.21 SY Flooring
29.67 LF Ceil. Perimeter



BuilldEstimatePro

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Air mover axial fan (per 24 hour period) - No monitoring	1.00 EA	0.00	30.00	0.00	30.00
Apply anti-microbial agent to the walls	46.85 SF	0.00	0.24	0.11	11.35

Rooms: Laundry



Utility Room					
QTY	REMOVE	REPLACE	TAX	TOTAL	
Walls	538.67 SF Walls			277.52 SF Ceiling	
Walls & Ceiling	816.19 SF Walls & Ceiling			277.52 SF Floor	
Flooring	30.84 SY Flooring			67.33 LF Floor Perimeter	
Ceil. Perimeter	67.33 LF Ceil. Perimeter				
			0.67	251.23	
			3.99	1,796.71	

ied

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Air mover axial fan (per 24 hour period)	1.00 EA	0.00	30.00	0.00	30.00
Anti-microbial agent to the walls	3.00 EA	0.00	51.32	0.00	153.96
Anti-microbial agent to the ceiling	277.52 SF	0.00	0.24	0.67	67.27
				0.67	251.23
			3.99	1,796.71	

CONTINUED - Labor Minimums Applied

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Totals: Labor Minimums Applied				0.00	612.48
Line Item Totals: GEORGE_BATCHVAROV				3.99	2,409.19

Grand Total Areas:

2,997.33 SF Walls	1,181.87 SF Ceiling	4,179.21 SF Walls and Ceiling
1,181.87 SF Floor	131.32 SY Flooring	374.67 LF Floor Perimeter
0.00 SF Long Wall	0.00 SF Short Wall	374.67 LF Ceil. Perimeter

BuilldEstimatePro

1,181.88 Floor Area
2,158.50 Exterior Wall Area

1,284.96 Total Area
239.83 Exterior Perimeter
of Walls

2,997.33 Interior Wall Area

0.00 Surface Area
0.00 Total Ridge Length

0.00 Number of Squares
0.00 Total Hip Length

0.00 Total Perimeter Length

BuilldEstimatePro

Summary for Dwelling

Line Item Total	2,405.20
Material Sales Tax	3.99=
Replacement Cost Value	\$2,409.19
Net Claim	\$2,409.19

BuilldEstimatePro

Recap by Room

Estimate: GEORGE_BATCHVAROV

Area: Main Level

Kitchen
Laundry
Utility Room

360.40	14.98%
1,140.52	47.42%
41.24	1.71%
250.56	10.42%

Area Subtotal: Main Level

Labor Minimums Applied

1,792.72	74.54%
612.48	25.46%

Subtotal of Areas

2,405.20	100.00%
----------	---------

Total

2,405.20	100.00%
----------	---------

Recap by Category

Total %

129.16 5.36%

45.70 1.90%

247.46 10.27%

333.49 13.84%

95.34 3.96%

194.09 8.06%

4.60 0.19%

1,355.36 56.26%

2,405.20 99.83%

3.99 0.17%

2,409.19 100.00%