date: 2002/08/07

# HITACHI SEMICONDUCTOR TECHNICAL UPDATE

Classification of Production	MPU			No	TN-SH7-419A/E	Rev	1
THEME	Errata in AC Characteristics of SH7751R	Classification of Information		<ol> <li>Spec change</li> <li>Supplement of Documents</li> <li>Limitation of Use</li> <li>Change of Mask</li> <li>Change of Production Line</li> </ol>			
	SH7751R	Lot No.		SH7751 series Hardware manual Rev 3.0 (ADE-602-201B)			fective Date
PRODUCT NAME		ALL	Reference Documents			Eternit	у

There are some errata in the hardware manual.

The correct specifications are as follows.

#### 1. Contents

## (1)Current descriptions in the hardware manual

## **Table 23.12 Clock Timing (HD6417751RBP240)**

Item		Symbol	Min	Тур	Max	Unit
Operating	CPU, FPU, cache, TLB	f	1	_	240	MHz
Frequency	External bus		1	_	84	
	Peripheral modules		1	_	60	

### Table 23.19 Clock and Control Signal Timing (HD6417751RF240)

Item	Symbol	Min	Max	Unit
CKIO clock output	fop	1	84	MHz
(PLL1/PLL2 not operat	ing)			

### (2)Correct specifications

## **Table 23.12 Clock Timing (HD6417751RBP240)**

Item		Symbol	Min	Тур	Max	Unit
Operating	CPU, FPU, cache, TLB	f	1		240	MHz
frequency	External bus		1		120	
	Peripheral modules		1		60	

### Table 23.19 Clock and Control Signal Timing (HD6417751RF240)

Item	Symbol	Min	Max	Unit
CKIO clock output	fop	1	34	MHz
(PLL1/PLL2 not operating	;)			