date: 2003/01/31

# HITACHI SEMICONDUCTOR TECHNICAL UPDATE

Classification of Production	Development Environment			No	TN-OS*-072A/E	Rev	1	
ТНЕМЕ	HI7700/4 V1.2.00 Updates Classification of Information		2. St 3. Li 4. C	<ol> <li>Limitation of Use</li> <li>Change of Mask</li> </ol>				
PRODUCT NAME	HS0770ITI41SRE, HS0770ITI41SRE-E, HS0770ITI41SRB, HS0770ITI41SRB-E, HS0770ITI41SRS, HS0770ITI41SRS-E	Lot No.  Show below	V1.00r1, V1.01r1, V1.0Ar1, V1.0Br1, V1.0Cr1, V1.1.00	Show b	pelow		Effective Date  Eternity	

The HI7700/4 is updated in V1.2.00.

## ♦ The "HI7000/4 series User's Manual" is revised

[English] Rev.1 (ADE-702-248) --> Rev.2 (ADE-702-248A)

[Japanese] Rev.2 (ADJ-702-298A) --> Rev.3 (ADJ-702-298B)

The main contents of change in a revised edition manual are as follows.

- (1) The contents of "HI7000/4 series User's Manual supplemental information (Rev.4)"(E702248-ERR-020315) are reflected in the revised edition manual.
- (2) The contents of TECHNICAL UPDATE "HI7750/4 Notes on using FPU" (TN-OS\*-066A/E) are reflected in the revised edition manual.
- (3) The descriptions of the new function of HI7700/4 V1.2.00 are added in the revised edition manual.

## **♦ New Functions**

The functions of the following which set power-saving as the main purpose are supported.

- (1) Optimized Timer Driver ... see Appendix E in the revised edition manual
- (2) DSP Standby Control Function ... see Appendix F in the revised edition manual

#### **♦ Bugs Fix**

This version fixes the following problems and the problems which have been reported with the TECHNICAL UPDATE "HI7700/4 and HI7750/4 Bugs regarding ref\_alm"(TN-OS\*-063A/E) and "HI7700/4 Problems" (TN-OS\*-070A/E).

### **♦ Download**

Please download HI7700/4 V1.2.00 from the following URL.

URL: http://www.hitachisemiconductor.com/sic/jsp/japan/eng/products/mpumcu/tool/download/itron.html