date: 2002/09/24

HITACHI SEMICONDUCTOR TECHNICAL UPDATE

Classification of Production	Development environment			No	TN-EML-096A/E	Rev.	1	
THEME	Problem on Using the PCMCIA and PCI Drivers for Windows® 2000 with the E10A/E10T/E6000/E8000 Emulator		Classification of Information	Spec change Supplement of Documents Limitation of Use		5. Change	Change of Mask Change of Production Line	
PRODUCT NAME	E10A/E10T/E6000/E8000 Emulator	Lot No. PCMCIA and PCI drivers for Windows 2000 dated May/2000 or before	Reference Documents		None	Effective Permanent	Effective Date Permanent	

The E10A/E10T/E6000/E8000 emulator may not be started up correctly when the emulator is connected to certain host computer, for which Windows[®] 2000 or Windows[®] XP has been installed, via the PCMCIA or PCI interface.

[Countermeasure]

- (1) Select the emulator you use and download the driver software for correction from the following URL address: http://www.hitachisemiconductor.com/sic/jsp/japan/eng/products/mpumcu/tool/download_index.html
- (2) Expand the file that you have downloaded. Then follow the installation procedure that is attached.

Note: Windows[®] is a registered trademark of Microsoft Corporation in the United States.