Date: Jun.24.2004

# **RENESAS TECHNICAL UPDATE**

Nippon Bldg., 2-6-2, Ohte-machi, Chiyoda-ku, Tokyo 100-0004, Japan RenesasTechnology Corp.

Product Category	User Development Environment		Document No.	TN-CSX-077A/EA	Rev.	1.0
Title	SuperH RISC engine C/C++ Compiler ver.7 Known Bugs Report(12)		Information Category	Usage Limitation		
Applicable Product	P0700CAS7-MWR P0700CAS7-SLR P0700CAS7-H7R	Lot No.		SuperH RISC engine C/C++ Compiler		
		Ver.7.x	Reference Document	Assembler Optimizing Linkage Editor User's Manual REJ10B0047-0100H Rev.1.00		

Attached is the description of the known bugs in Ver. 7 series of the SuperH RISC engine C/C++ compiler.

The bugs will affect the package version in the table below.

	Package Version	Compiler Version
	7.0B	7.0B
	7.0.01	7.0.03
	7.0.02	7.0.04
	7.0.03	7.0.06
P0700CAS7-MWR	7.1.00	7.1.00
	7.1.01 7.1.02	7.1.01
	7.1.02	7.1.02
	7.1.04	7.1.03
	7.0B	7.0B
	7.0.02	7.0.03
	7.0.03	7.0.04
	7.0.04	7.0.06
P0700CAS7-SLR	7.1.00	7.1.00
	7.1.01 7.1.02	7.1.01
	7.1.03	7.1.02
	7.1.04	7.1.03
	7.0B	7.0B
	7.0.02	7.0.03
	7.0.03	7.0.04
	7.0.04	7.0.06
P0700CAS7-H7R	7.1.00	7.1.00
	7.1.01 7.1.02	7.1.01
	7.1.02	7.1.02
	7.1.04	7.1.03

Attached: P0700CAS7-040611E

SuperH RISC engine C/C++ Compiler Ver. 7 Known Bugs Report (12)

# SuperH RISC engine C/C++ Compiler ver.7 Known Bugs Report(12)

The bugs detected in the ver.7 of the SuperH RISC engine C/C++ Compiler is shown below.

1. Incorrect removing of sign/zero extension instruction in an expression in a switch statement [Description]

When a 1- or 2-byte parameter was used as an expression in a switch, sign/zero extension expression was removed incorrectly, then the destination address might be incorrect.

```
[Example]
```

```
int func(short x) {
   short r = -1;
switch(x) {
   case 0: r = 0; break;
   case 1: r = 1; break;
   case 2: r = 2; break;
   case 3: r = 3; break;
   case 4: r = 4; break;
   case 5: r = 5; break;
   case 6: r = 6; break;
   case 7: r = 7; break;
   case 8: r = 8; break;
   return (r);
}
_func:
       MOV
                 R4,R2
                          ; The upper 2 bytes of R4 are undefined value.
       EXTS.W
                 R4,R4
                 #8,R3
       MOV
       CMP/HI
                 R3,R4
       MOV
                 #-1,R6
       BT
                L23
                          ; Shift value without sign/zero extension
       SHLL
                 R2
       MOVA
                 L25,R0
                 @(R0,R2),R1
       MOV.W
       ADD
                 R1,R0
       JMP
                 @R0
       NOP
L24:
L25:
       .DATA.W
                  L12-L25
       .DATA.W
                  L13-L25
```

## [Conditions]

This problem might occur when all of the following conditions were fulfilled.

- (1) The optimize=1 option was specified.
- (2) A function had a 1- or 2-byte parameter.
- (3) The function of (2) had a switch statement.
- (4) An expression in the switch had the its parameter.
- (5) The switch statement was generated as the jumping to a table expansion method.

# [Solution]

If a relevant failure exists, prevent the problem by one of the following methods.

- (1) Specify optimize=0.
- (2) Apply explicitly cast to the type of the parameter to the expression in the switch statement. Example: switch((short)x)
- (3) Declare the parameter as volatile.

# 2. Incorrect removing of zero extension instruction [Description]

When an unsigned char/unsigned short type variable was referred to twice or more in a loop, zero extension instruction might be removed illegally.

# [Example]

```
MOV.B @Rm,Rn
EXTU.B Rn, Rn; Clear the upper three bytes
:
MOV.B Rn,@R15; Assign to a stack
:
MOV.B @R15,R12; Assign to R12
=> EXTU.B R12,R12 was removed illegally
L1:
:
CMP/EQ R12,R2; a value of R12 was incorrect
:
BT L1
```

# [Conditions]

This problem might occur when all of the following conditions were fulfilled.

- (1) The optimize=1 option was specified.
- (2) An unsigned char/unsigned short type variable existed.
- (3) The variable of (2) was referred to twice or more in a loop.
- (4) The variable of (2) was not assigned to a register.
- (5) A register which was not used in the loop of (3) existed.
- (6) The register of (5) was used out of the loop.

# [Solution]

If a relevant failure exists, prevent the problem by the following method.

(1) Specify optimize=0.

3. Incorrect calculation of quadratic expression of loop induction variable [Description]

If a quadratic expression had a loop induction variable i of the form "m \* (i \* i + b \* i)", the expression might be treated as incorrectly.

```
[Example]
  int a[100];
  f() {
    int i;
    for (i=0;i<100;i++){
        a[i] = 3 * (i * i + 555 * i); /* incorrectly expanded as 3*i*i+555*i */
    }
}</pre>
```

# [Conditions]

This problem might occur when all of the following conditions were fulfilled.

- (1) The optimize=1 option was specified.
- (2) A loop existed.
- (3) The loop of (2) had int/unsigned int/long/unsigned long-type loop induction variable.
- (4) A quadratic expression had the loop induction variable of (3) in the loop of (2).
- (5) The expression of (4) had the form of "m\*(i\*i+b\*i)".
  - (i : loop induction variable m,b : variable or const value)

#### [Solution]

If a relevant failure exists, prevent the problem by one of the following methods.

- (1) Specify optimize=0.
- (2) Declare the loop induction variable as volatile.
- (3) Declare the loop induction variable as other than int/unsigned int/long/unsigned long type variable.
- (4) Distribute coefficient m of the quadratic expression to i\*i and b\*i.

```
Example: 3*(i*i+555*i) => 3*i*i+3*555*i
```

4. Incorrect removing of sign/zero extension instruction in the addition/subtraction/multiplication [Description]

When an addition/subtraction/multiplication was assigned to a variable with the type of smaller size or cast to the type of smaller size, and the result was used for addition/subtraction/multiplication, sign/zero extension might be removed incorrectly.

```
[Example]
  int x,a;
  test_000()
     char b;
     b = (char)(a + 3);
     x = b + 2i
_f:
         MOV.L
                   L11,R6
         MOV.L
                   L11+4,R2 ; _x
         MOV.L
                   @R6,R6
         ADD
                   #5,R6
                            ; cast to char type was removed illegally
                         ; and a+5 was assigned to the variable x.
         RTS
                   R6,@R2
         MOV.L
```

### [Conditions]

This problem might occur when all of the following conditions were fulfilled.

- (1) The optimize=1 option was specified.
- (2) An addition/subtraction/multiplication had either of operands was a constant value.
- (3) One of the following conditions (a)(b) was fulfilled.
  - (a) The result of (2) was cast to the type of smaller size, and the result was used for addition/subtraction/multiplication.
  - (b) The result of (2) was assigned to a variable with the type of smaller size, and the result was used for addition/subtraction/multiplication.

### [Solution]

If a relevant failure exists, prevent the problem by one of the following methods.

- (1) Specify optimize=0.
- (2) Assign the result of the condition (2) to a variable which is declared as volatile.

5. Incorrect removing of sign/zero extension of a constant division (SHC-0001) [Description]

When a divisor and a dividend were cast to the type of smaller size at a constant division and the result of the division or the residue was assigned to a variable with a type after the cast, the cast might be removed illegally.

c = ((char)i / (char)0x102); /\* a divisor was not changed into 0x2 \*/

```
[Example]
   char c;
   int i;
   func1(){
      c = ((char)i / (char)2); /* a dividend was not cast to char type */
   }
   func2(){
```

# [Conditions]

This problem might occur when all of the following conditions were fulfilled.

- (1) The optimize=1 option was specified.
- (2) A constant division existed.
- (3) A divisor and a dividend ware cast to the type of smaller size at a constant division of (2).
- (4) The divisor was a power of 2, or other than cpu=sh1 option and the division=cpu=inline option were specified.
- (5) The result of the division was assigned to a variable with a type after the cast.

#### [Solution]

If a relevant failure exists, prevent the problem by one of the following methods.

- (1) Specify optimize=0.
- (2) Delete the cast of the divisor and replace the divisor by a value after the cast.

```
Example func1(): c = ((char)i / (char)2); => c = ((char)i / 2); func2(): c = ((char)i / (char)0x102); => c = ((char)i / 0x02);
```

(3) Assign the result of the division to a int-type variable.

```
Example func1(): tmp = ((char)i / (char)2); (tmp : int-type variable) c = (char)tmp;
```