date: 2002/03/14

HITACHI SEMICONDUCTOR TECHNICAL UPDATE

Classification of Production	Development Environment					No	TN-CSX-033A/E	
ТНЕМЕ	Note on using Optimizing Linkage Editor SuperH RISC engine C/C++ Compiler Package H8S.H8/300 C/C++ Compiler Package H8S.H8/300 C/C++ Compiler Package Docume		Spec change Supplement Documents Limitation of	of	Change of Mask Change of Production Line			
PRODUCT NAME	SH-1, SH2, SH-2E,SH2-DSP, SH-3, SH-3DSP, SH-4 H8/300, H8/300L, H8/300H, H8S/2000, H8S/2600	Lot No.					Rev.	Effective Date
		All	Reference Documents		_ 		1	Eternity

The linkage editor might have a problem in the condition below.

[Products]

C/C++ Compiler Package

PS008CAS4-MWR (Target V/R: 4.0A, 4.0AR1, 4.0AR2)

PS008CAS5-MWR (Target V/R: 5.0, 5.0.01)

P0700CAS6-MWR (Target V/R: 6.0A, 6.0AR1, 6.0AR2)

P0700CAS7-MWR (Target V/R: 7.0B, 7.0.01)

[Conditions]

Optimizing Linkage Editor: V7.0A, V7.1, V7.1.02 or later

Operating System: Microsoft^(R) Windows^(R) 2000 (Service Pack 1)

[Symptom]

Time for linkage can be extremely long on the OS above.

[How to escape the symptom]

Please update Service Pack 1 to Service Pack 2 of Windows^(R) 2000.