HITACHI MICROCOMPUTER TECHNICAL UPDATE

DATE	30 August 2001	No.		TN-SH7-349A/E		
THEME	About initial value of bypass register.					
CLASSIFICATION	☐ Spec change ☐ Limitation on Use ☐ Supplement of Documents					
PRODUCTNAME	HD6417750 HD6417750S HD6417751			Lot	Lot#:All	
REFERENCE	RENCE SH7750 series Hardware Manual (Rev.1-4)		ev.	Effectiv		
DOCUMENTS	SH7751 Hardware Manual (Rev.1-2)			Eterni	ty	
When using bypass mode of SH-4 H-UDI function, pay attention to the following item: 1. Contents In IEEE Std 1149.1, there is prescription on the bypass mode as follows. When the TAP controller transfers to Capture-DR State, the bypass register is set to logic 0.						
On the other hand, in SH-4, When the TAP controller transfers to Capture-DR State, the bypass register has an undefined value.						
2. Workaround Do not transfer the data expecting the fact that the bypass register is set to logic 0 when the TAP controller transfers to Capture-DR State on bypass mode.						