

INCIDENT REPORT

Code: NCM-HSSE-INR-0031

Incident Details

Incident Reference No : NCM-HSSE-INR-0031 Company Name : Vision Safety LLC

Reported By : Lijo.Paulose@visionsafety.ae Mobile Number : 0565265609

Incident Category : Health & Safety Incident Type : Dangerous occurrence

Date And Time Of : 13-Mar-2024 Reported Time : 16-Mar-2024

7:59AM 7:58AM

Business Unit : Community Management Zone : Zone 1

Building : PJ-MR-EAST Community : Marina Residences

Is There Any : No Location : Marina Residences 3

Injury/Illness?

Incident

Incident Party : Others Name : Vision Safety

Follow Up Required? : No

Description : VS TEAM ATTENDED FIRE FIGHTING CALL OUT ON 13/03/2024AT 07.59 HRS FROM SECURITY

TEAM, REGARDS THE LEAKAGE OF FIRE FIGHTING LINE WHICH IS LOCATED IN MARIA

RESIDENCE 3-BASEMENT 1 NEAR PARKING B-288.

DURING THE INVESTIGATION TEAM OBSERVED THAT THE FIRE FIGHTING LINE MECHANICAL

TEE DAMAGED.

· VS TEAM OBSERVED THAT MECHANICAL TEE GOT DAMAGED DUE TO AGED FACT.

 \cdot VS TEAM REPLACED MECHANICAL TEE ON PRIORITY TO RESTORE THE SPRINKLER SYSTEM TO

USE THE NEW MATERIALS.

• ZONE CONTROL VALVE IS OPEN & FIRE PUMPS ARE IN AUTO MODE.

· VS TEAM OBSERVED THAT FIRE FIGHTING LINES ARE ENERGIZED AND SYSTEM HAVING NO

LEAKAGES.

Immediate Actions Taken : · VS TEAM REPLACED MECHANICAL TEE ON PRIORITY TO RESTORE THE SPRINKLER SYSTEM TO

USE THE NEW MATERIALS.

· ZONE CONTROL VALVE IS OPEN & FIRE PUMPS ARE IN AUTO MODE.

· VS TEAM OBSERVED THAT FIRE FIGHTING LINES ARE ENERGIZED AND SYSTEM HAVING NO

LEAKAGES.

Evidence



