












1	2	3	4	5	
A					A
B					B
C					C
D					D
1	2	3	4	5	


TITLE: Power			REV: 1.0
	Company:		Sheet: 1/1
	Date: 2026-01-07 Drawn By: eng. Michael B.		

ESD Protection




NOTE: put close to PCB output terminals

Supply fuses



NOTE: ADD TVS for 5V and 3V3 lines to avoid over voltage

TITLE: Fuses		REV: 1.0
EasyEDA	Company:	Sheet: 1/1
	Date: 2026-01-13	Drawn By: eng. Michael B.



TITLE: Inputs		REV: 1.0
	Company:	Sheet: 1/1
	Date: 2026-01-13 Drawn By: eng. Michael B.	

1	2	3	4	5
A				A
B				B
C				C
D				D
1	2	3	4	5

TITLE: Outputs			REV: 1.0
	Company:		Sheet: 1/1
	Date: 2026-01-13 Drawn By: eng. Michael B.		