Appendix

1	:	
Inte	rvi	ew

Transcript:	

Problems: (Provided by the client)

- 1. Photogates don't always work unless they are going straight through the middle of the mass. This causes the timing ot be off.
- 2. Tracking the pendulum throughout the entire swing.
- 3. Raw data is the most important.