FORMULEBLAD

RLC

$$X_{C} = \frac{1}{2\pi fC}$$

$$X_1 = 2\pi fL$$

$$f_r = \frac{1}{2\pi\sqrt{LC}}$$

Serie

$$I_T = \frac{V_T}{Z}$$

$$V_L = I X$$

$$V_C = I X_C$$

$$V_{\tau} = IZ$$

$$Q = \frac{X_L}{Z} = \frac{X_C}{Z} = \frac{V_L}{V_C} = \frac{V_C}{V_C} = \frac{1}{R} \sqrt{\frac{L}{C}}$$

$$Z = \sqrt{R^2 + (X_L - X_C)^2}$$

$$Z = \sqrt{R^{2} + (X_{L} - X_{C})^{2}}$$

$$V_{T} = \sqrt{V_{R}^{2} + (V_{L} - V_{C})^{2}}$$

$$\cos \theta = \frac{R}{Z}$$

$$\cos \theta = \frac{V_R}{V_T}$$

Parallel

$$\cos \theta = \frac{I_R}{I_T}$$

$$I_{T} = \sqrt{I_{R}^{2} + \left(I_{L} - I_{C}\right)^{2}}$$

$$I_R = \frac{V_R}{R}$$

$$I_C = \frac{V_C}{X_C}$$

$$I_L = \frac{V_L}{X_L}$$

$$Q = \frac{X_L}{Z} = \frac{X_C}{Z} = \frac{I_L}{I_S} = \frac{I_C}{I_S} = \frac{1}{R} \sqrt{\frac{L}{C}}$$

$$BW = \frac{f_r}{Q}$$

HALFGELEIERTOESTELLE

Wins
$$A_V = \frac{V_{uit}}{V_{in}} = -\left(\frac{RF}{R_{in}}\right)$$

$$V_{uit} = V_{in} \times \left(-\frac{R_F}{R in} \right)$$

$$V_{UIT} = V_{IN} \times \left(1 + \frac{R_F}{R_{in}}\right)$$

SKAKELKRINGE

$$V_{uit} = V_{in}1 \times \left(-\frac{R_F}{R1}\right) + V_{in}2 \times \left(-\frac{R_F}{R2}\right) + \dots V_{in}N \times \left(-\frac{R_F}{RN}\right)$$
$$V_{uit} = -\left(V_1 + V_2 + V_3 + \dots V_N\right)$$

VERSTERKERS

$$I_{\rm C} = \frac{V_{\rm C}}{R_{\rm c}}$$

$$V_{CC} = V_{CF} + I_{C}R_{C}$$

$$A = \beta_1 \times \beta_2$$

$$A_{i} = 20log \frac{I_{0}}{I_{i}}$$

$$A_{V} = 20log \frac{V_{O}}{V_{i}}$$

$$P_0 = I^2 \times Z_0$$

$$A_{P} = 10log \frac{P_{O}}{P_{i}}$$

$$A_{v(dB)} = 20log A_{v}$$

Wins
$$A_V = \frac{V_{uit}}{V_{in}} = -\left(\frac{RF}{R_{in}}\right)$$

$$f_O = \frac{1}{2\pi\sqrt{L_T C}}$$

Hartley-ossillator

$$f_0 = \frac{1}{2\pi\sqrt{LC_T}}$$
 Colpitts-ossillator

$$f_{O} = \frac{1}{2\pi\sqrt{6RC}}$$

 $f_0 = \frac{1}{2\pi\sqrt{6RC}}$ RC-faseverskuiwingsossillator