

TRUCK GROUP

# SAFETY RECALL 07511

# SEPTEMBER 2007

Dear International Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

International® has decided that a defect which relates to motor vehicle safety exists in the Bendix® SR-7™ Spring Brake Modulating Valve of certain 5900*i*, 7000 and 8600 models built 11/1/2005 thru 4/30/2007

## REASON FOR THIS RECALL

An internal check valve in the SR-7 Spring Brake Modulating Valve may not properly seat, causing internal air leakage. This internal leakage can cause a delay in the application of the spring brakes to park the vehicle after the operator pulls the dash valve button. A delay in the application of the spring brakes can contribute to a vehicle roll away.

## RISK TO MOTOR VEHICLE SAFETY

A vehicle roll away can cause a vehicle crash, possibly resulting in property damage or personal injury.

#### ACTIONS YOU SHOULD TAKE

PLEASE contact your local International dealer to schedule an appointment to have your vehicle repaired. You may locate your nearest International dealer by calling 1-800-44-TRUCK or by visiting:

## http://www.nav-international.com

The repair will involve a replacement of an internal check valve cartridge.

Dealers will have parts and instructions to repair your vehicle by 9/14/2007.

This will be performed *free of charge* and may take approximately *30 minutes* to complete.

You may already have been notified of Safety Recall G-06506 for a similar issue. If you have had the remedy forG-06506 performed, you are *still required* to have *this* Safety Recall performed.

#### IF YOU DO NOT OWN THIS VEHICLE

Our records indicate you are the owner of the vehicle identified on the enclosed card. If you do not own this vehicle, please fill out the **Authorization for Recall Service** card so you will not be contacted again regarding this recall.

# IF YOU NEED ASSISTANCE

If you believe that International has failed to perform this repair within a reasonable amount of time, or the existing condition was not remedied without charge, please follow the procedure described in the *Owner Assistance Guide* section in your Owner's Manual or call toll free 1-800-448-7825.

You may also wish to submit a complaint to:

Administrator National Highway Traffic Safety Administration, 1200 New Jersey Ave. S.E. Washington, D.C., 20590

or call the toll-free Vehicle Safety Hot-Line at 1-888-327-4236 (TTY:1-800-424-9152) or go to <a href="http://www.safercar.gov">http://www.safercar.gov</a>.

## LESSOR REQUIREMENTS

Federal regulations require that any vehicle lessor receiving this Recall notice must forward a copy of this notice to the lessee within ten days.

## REIMBURSEMENT ELIGIBILITY

If you have previously paid for repairs as a result of this defect, you may be entitled to recovery of those expenses. Contact your dealer for details

We request your prompt attention to the correction of this defect and apologize for any inconvenience this may cause you.

Sincerely,

# INTERNATIONAL TRUCK AND ENGINE CORPORATION