

### INTERNATIONAL TRUCK AND ENGINE CORPORATION

4201 WINFIELD ROAD, WARRENVILLE, IL 60555

TRUCK GROUP

#### NONCOMPLIANCE RECALL 03501

February 2003

Dear International Customer:

This noncompliance recall is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. International is recalling 3200, 4200, 4300, and 4400 model vehicles built from 7/16/02 through 1/14/03 that do not have the required components to operate the hydraulic brake warning light. International has decided that these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) 105 section 5.3.1.

Our records show that you are the owner of the vehicle on the enclosed card. If you are not the owner, we need your help finding the current owner; thus, **please** read paragraph number 4 under "ACTIONS YOU SHOULD TAKE."

# **REASONS FOR THIS RECALL**

#### NONCOMPLIANCE DESCRIPTION

Your vehicle was built without the hydraulic brake monitor module. Without this brake monitor module, the brake warning light will not come on to warn the operator if there is a loss of hydraulic pressure in the brake system, a loss of power steering flow or if the emergency brake booster motor is not functioning.

# <u>ACTIONS YOU SHOULD TAKE</u>

1. Our records show that you are the owner of the vehicle identified on the enclosed card. If you are not the owner, please read paragraph number 4.

- 2. Please contact your local International dealer, with your recall card in hand, to schedule an appointment to have your vehicle repaired. All vehicles involved in this recall must have the hydraulic brake monitor module installed. This repair will be performed without charge to you and will take approximately one hour. Have your dealer verify and correct your address if necessary. If your local International dealer performs the repair, they will submit a warranty claim; therefore, you DO NOT have to mail in the campaign card.
- 3. If the vehicle will not or cannot be corrected, please mark on the enclosed card under "CHECK ONE", the box which best describes why the vehicle will not be repaired, and return the postage-prepaid card to us.
- 4. In the event you do not own the vehicle described on the card, please complete the card, fill in the new customer name and address if known, and return it to us. This information will allow us to update our records so we can contact the new owner and you will not be contacted again regarding this recall.

### IF YOU NEED ASSISTANCE

If you take your vehicle to your International dealer on a mutually agreed upon service date, and the dealer does not remedy this condition without charge on that date or within five days, you can obtain assistance by following the procedure described in the Owner Assistance Guide section in your Owner's Manual, or by calling toll free 1-800-448-7825.

You may also wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C., 20590, or call the Administration's toll-free Auto Safety Hot-Line at 1-888-327-4236 if your International dealer fails to repair or is unable to remedy this condition without charge or within a reasonable time.

We urge your prompt attention to the correction of this noncompliance and apologize for any inconvenience this may cause.

INTERNATIONAL TRUCK AND ENGINE CORPORATION