

INTERNATIONAL TRUCK AND ENGINE CORPORATION

4201 WINFIELD ROAD, WARRENVILLE, IL 60555

.....

TRUCK GROUP

RECALL REMINDER NOTICE G-03508 March 2005



THIS IS AN ISIS ONLY NOTIFICATION.

There will be NO Dealer Mailing for this RECALL REMINDER.

Please refer to the dealer letter G-03508 for service instructions.

SUBJECT: SAFETY RECALL (U.S., EXPORT)

Tail Pipe Exhaust Single Band Clamp on 9000 Series Models built 11/15/2002 through 3/12/2003 with Caterpillar Engines.

The single band clamp on the tail pipe can lose its clamping ability under normal driving conditions causing the pipe to loosen and potentially fall off of the vehicle. The pipe could come off without warning and fall into the path of other vehicles on the highway, possibly resulting in **a crash without warning**.

This letter is to inform you that the *owners* of suspect vehicles who have not completed the Recall Service Procedure, have been sent a reminder to schedule an appointment to have the service performed.

We appreciate your patience and cooperation regarding this campaign and apologize for any inconvenience this may cause.

INTERNATIONAL TRUCK AND ENGINE CORPORATION