

INTERNATIONAL TRUCK AND ENGINE CORPORATION

4201 WINFIELD ROAD, WARRENVILLE, IL 60555

.....

TRUCK GROUP

RECALL REMINDER FOR SAFETY RECALL 03514

February 2005

Dear International Truck Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. International has decided the **air tank plumbing** of certain 4000 Series models built 8/27/2002 through 7/22/2003 with side-by-side, outside frame rail air tanks are not compliant to Federal Motor Vehicle Safety Standard (FMVSS) 121 Section 5.7.1 and may pose a risk to motor vehicle safety.

The vehicle identified on the attached card fits this description. *Our records show that you own this vehicle and were sent an initial Safety Recall Notification in September of 2003.* Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

The 5/8" green and orange air hoses between the brake treadle valve and primary and secondary air tanks were possibly routed incorrectly.

If a failure of the primary air circuit occurs with the incorrect hose plumbing, depressing the brake pedal will not engage the brake chambers and possibly cause a motor vehicle crash without warning, possibly resulting in property damage, personal injury, or death.

In the event you no longer own the vehicle described on the card, please complete the card, fill in the new customer name and address if known, and return it to us. This information will allow us to update our records so that we can contact the current owner and you will not be contacted again regarding this recall.

Please contact your local International dealer to schedule an appointment and have the service procedure completed. Be prepared to read your vehicle identification number from your attached card, when you call to schedule an appointment. The remedy is to reroute the air hoses to the proper locations. The repair will be made without charge to you and will require approximately 1 hour of repair time.

ALL VEHICLES IN THIS SAFETY RECALL MUST BE CORRECTED.

If the vehicle will not or cannot be corrected, please mark on the attached card the box which best describes why the vehicle will not be repaired, and return the postage-prepaid card to us.

WE URGE YOUR PROMPT ATTENTION TO THE CORRECTION OF THIS SAFETY DEFECT AND APOLOGIZE FOR ANY INCONVENIENCE THIS MAY CAUSE YOU.

INTERNATIONAL TRUCK AND ENGINE CORPORATION

AUTHORIZATION FOR RECALI
SERVICE REMINDER

Model Name	Vehicle Identification Number (VIN)	TSR	Dealer Code	Campaign #



Please check only one (1) of the following:

- 1 ☐ Vehicle inspected no corrections necessary.
- $2 \square$ Vehicle corrections completed.
- 3 □ I do not own this vehicle any more.
 (Please complete the NEW OWNER INFORMATION block)
- 4 ☐ Service Not Desired. Reason:_
- $5 \ \square$ Vehicle Scrapped (junked). Will not return to public streets.
- 6 □ Vehicle Stolen (whereabouts unknown).
- 7 □ Vehicle exported from U.S. to another country.

 (Please complete the NEW OWNER INFORMATION block)

New Owne	r Information		
Name			_
Street			
City	State	Zip	

Recall Reminder Business Reply