

#### INTERNATIONAL TRUCK AND ENGINE CORPORATION

4201 WINFIELD ROAD, WARRENVILLE, IL 60555

.....

TRUCK GROUP

# RECALL REMINDER NOTICE G-03503 February 2005



## THIS IS AN ISIS ONLY NOTIFICATION.

There will be NO Dealer Mailing for this RECALL REMINDER.

Please refer to the dealer letter G-03503 for service instructions.

# SUBJECT: SAFETY RECALL (U.S., EXPORT)

Limiting the forward travel on the driver's seat by installing a stop-bracket on the adjuster track for 4700 models built from 12/13/94 through 9/4/98.

International has decided that a defect related to motor vehicle safety exists in the driver's seat. The vehicles involved are 4700 models built from 12/13/94 through 9/4/98 with one of the following Bostrom driver's seat models: 910, 910SC, or 914 and with International's parking brake code 04036.

This letter is to inform you that the *owners* of suspect vehicles who have not completed the Recall Service Procedure, have been sent a *second* reminder to schedule an appointment to have the service performed.

We appreciate your patience and cooperation regarding this campaign and apologize for any inconvenience this may cause.

### INTERNATIONAL TRUCK AND ENGINE CORPORATION