

INTERNATIONAL TRUCK AND ENGINE CORPORATION

4201 WINFIELD ROAD, WARRENVILLE, IL 60555

TRUCK GROUP

SAFETY RECALL 07507

JUNE 2007

Dear International Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

International® has decided that a defect which relates to motor vehicle safety exists in certain 9000 models built 7/20/2006 thru 3/19/2007 with feature code 0012WTK – AUXILIARY POWER No Idle Solution.

REASON FOR THIS RECALL

The diesel engine/generator unit can be started remotely by a person in the truck cab while its protective cover is removed; and under certain conditions the engine may re-start after the emergency fuel cutoff is used to shut down the unit.

RISK TO MOTOR VEHICLE SAFETY

An unexpected starting of the diesel engine/generator unit, when the protective cover is removed and maintenance is being performed, may result in personal injury.

ACTIONS YOU SHOULD TAKE

PLEASE contact your local International dealer to schedule an appointment to have your vehicle repaired. You may locate your nearest International dealer by calling 1-800-44-TRUCK or by visiting:

http://www.nav-international.com

The repair will involve a replacement of the under bunk HVAC unit, APU controller, cab controller and the addition of safety labels and orange loom on high voltage cables.

Dealers will have instructions to repair your vehicle by 6/29/2007.

The repair will be performed *free of charge* and may take approximately *2.5 hours* to complete.

NEW OPERATOR'S MANUAL

Included with this mailing is a revised operator's manual for your No-Idle APU/HVAC System. Please discard your old manual and replace it with the new one. Ensure this manual remains with your vehicle at all times.

IF YOU DO NOT OWN THIS VEHICLE

Our records indicate you are the owner of the vehicle identified on the enclosed card. If you do not own this vehicle, please fill out the **Authorization for Recall Service** card so you will not be contacted again regarding this recall.

IF YOU NEED ASSISTANCE

If you believe that International has failed to perform this repair within a reasonable amount of time, or the existing condition was not remedied without charge, please follow the procedure described in the *Owner Assistance Guide* section in your Owner's Manual or call toll free 1-800-448-7825.

You may also wish to submit a complaint to:
Administrator
National Highway Traffic Safety Administration,
1200 New Jersey Avenue, S.E.
Washington, D.C., 20590

or call the toll-free Vehicle Safety Hot-Line at 1-888-327-4236 (TTY:1-800-424-9152) or go to http://www.safercar.gov.

LESSOR REQUIREMENTS

Federal regulations require that any vehicle lessor receiving this Recall notice must forward a copy of this notice and revised operator's manual to the lessee within ten days.

We request your prompt attention and patience regarding the correction of this defect and apologize for any inconvenience this may cause you.

Sincerely,

INTERNATIONAL TRUCK AND ENGINE CORPORATION