

#### INTERNATIONAL TRUCK AND ENGINE CORPORATION

4201 WINFIELD ROAD, WARRENVILLE, IL 60555

TRUCK GROUP

# RECALL REMINDER NOTICE G-02515 October 2004



### THIS IS AN ISIS ONLY NOTIFICATION.

There will be NO Dealer Mailing for this RECALL REMINDER.

Please refer to the dealer letter G-02515 for service instructions.

## **SUBJECT: VEHICLE RECALL (U.S., EXPORT)**

Under-Torqued Brake Spider or Anchor Plate Mounting Bolts On The Right Side of Certain 9100i, 9200i, 9400i and 9900i Models Built Between 7/22/02 and 8/16/02

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. International has decided that a defect, which relates to motor vehicle safety, exists in the front and rear brakes on certain 9100i, 9200i, 9400i and 9900i models built from 7/22/02 through 8/16/02.

This letter is to inform you that the *owners* of suspect vehicles who have not completed the Recall Service Procedure, have been sent a reminder to schedule an appointment to have the service performed.

We appreciate your patience and cooperation regarding this campaign and apologize for any inconvenience this may cause.

#### INTERNATIONAL TRUCK AND ENGINE CORPORATION