

# INTERNATIONAL TRUCK AND ENGINE CORPORATION

4201 WINFIELD ROAD, WARRENVILLE, IL 60555

.....

TRUCK GROUP

SAFETY RECALL 04512

March 2005

Dear International Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. This is follow up notification to an earlier letter in which we had advised that International® had decided that a defect which relates to motor vehicle safety exists in the **power steering hose routing, engine harness routing, and oil pressure switch** of certain MODEL YEAR 2005 RE bus models built 3/3/2004 thru 8/5/2004 with I6 engines. Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

The vehicle identified on the attached card fits this description. Our records show that you own this vehicle and were sent an INTERIM ACTION Safety Recall Notification in August of 2004.

INTERNATIONAL has determined that the actions performed under the INTERIM ACTION G-04512 are an appropriate final remedy.

Our records show you have had the Interim Action G-04512 performed on the vehicle listed below, NO FURTHER ACTION IS REQUIRED from you regarding this Safety Recall.

# **REASON FOR THIS RECALL**

Several conditions that may exist in the engine compartment are as follows:

- The high-pressure supply hose from the power steering pump to the steering gear may chafe against the positive stud on the starter solenoid.
- The engine electrical harness, containing the positive cable from the alternator, may be pinched between the engine and the bus body.
- An optional oil pressure switch may have been damaged during manufacturing, causing a leak to form.

### **RISK TO MOTOR VEHICLE SAFETY**

Any of the above conditions may cause or contribute to a potential fire in the engine bay.

## **ACTION YOU SHOULD TAKE**

- 1. NO FURTHER ACTION IS NECESSARY.
- 2. Our records show that you are the owner of the vehicle identified on the enclosed card. If you are not the owner, please read paragraph number 3.
- 3. In the event you do not own the vehicle described on the card, please complete the card, fill in the new customer name and address if known, and return it to us. This information will allow us to update our records so we can contact the new owner and you will not be contacted again regarding this recall.

### IF YOU NEED ASSISTANCE

If you take your vehicle to your International dealer on a mutually agreed upon service date, and the dealer does not remedy this condition without charge on that date or within five days, you can obtain assistance by following the procedure described in the Owner Assistance Guide section in your Owner's Manual or by calling toll free 1-800-448-7825.

You may also wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C., 20590, or call the toll-free Auto Safety Hot Line at 1-888-327-4236 if your International dealer fails to repair or is unable to remedy this condition without charge or within a reasonable time.

We request your prompt attention to the correction of this defect and apologize for any inconvenience this may cause you.

# INTERNATIONAL TRUCK AND ENGINE CORPORATION