

INTERNATIONAL TRUCK AND ENGINE CORPORATION

4201 WINFIELD ROAD, WARRENVILLE, IL 60555

.....

TRUCK GROUP

RECALL REMINDER NOTICE G-04508 March 2006



THIS IS AN ISIS ONLY NOTIFICATION.

Please refer to the dealer letter G-04508 for service instructions.

SUBJECT:

SAFETY RECALL (U.S., EXPORT)

Kelsey-Hayes (Lucas Varity or TRW) Anti-Lock Brake (ABS) Electronic Control Unit on 1552, 1652, 4700 and 4900 truck models built 2/28/1999

thru 3/25/2004

The anti-lock brake system (ABS) electronic control unit may misinterpret a corrupt wheel speed signal. The corrupt wheel speed signals may improperly activate the ABS, instead of deactivating the ABS. This may result in the driver experiencing a hard pedal feel and a decrease in deceleration at the end of the stop, resulting in extended stopping distances which could cause a vehicle crash, possibly resulting in **property damage**, **personal injury**, **or death**.

This letter is to inform you that the *owners* of suspect vehicles who have not completed the Recall Service Procedure, have been sent a reminder to schedule an appointment to have the service performed.

We appreciate your patience and cooperation regarding this campaign and apologize for any inconvenience this may cause.

INTERNATIONAL TRUCK AND ENGINE CORPORATION