

#### INTERNATIONAL TRUCK AND ENGINE CORPORATION

4201 WINFIELD ROAD, WARRENVILLE, IL 60555

-----

TRUCK GROUP

SAFETY RECALL 05521

December 2005

Dear International Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. International® has decided that a defect which relates to motor vehicle safety exists in the **cab entry steps** of certain CF500 and CF600 models built between 6/2/2004 and 9/27/2005. The vehicle identified on the enclosed card fits this description and our records show that you own this vehicle. Federal regulations require that any vehicle lessor receiving this Recall notice must forward a copy of this notice to the lessee within ten days.

### REASON FOR THIS RECALL

The cab entry steps were manufactured incorrectly causing them to have lower material strength properties than designed. These lower material strength properties can allow the step tread to fracture and separate from the vehicle under normal usage.

#### **RISK TO MOTOR VEHICLE SAFETY**

Step-tread separation, while a person is entering or exiting the cab, may result in **property** damage or **personal injury**.

#### **ACTION YOU SHOULD TAKE**

- 1. Our records show that you are the owner of the vehicle identified on the enclosed card. If you are not the owner, please read paragraph number 6.
- **2.** Please contact your local International dealer, with your recall card in hand, to schedule an appointment to have your vehicle repaired.
- 3. Dealers will have parts and instructions to repair your vehicle by 12/9/2005. The repair will be performed without charge to you and will take approximately 45 minutes.
- 4. When your local International dealer performs the repair, they will submit a warranty claim; therefore, you **DO NOT** have to mail in the campaign card.

- **5.** If the vehicle cannot be corrected, please mark on the enclosed card under "CHECK ONE" the box which best describes why the vehicle can not be repaired, and return the postage-prepaid card to us.
- 6. In the event you do not own the vehicle described on the card, please complete the card, fill in the new customer name and address if known, and return it to us. This information will allow us to update our records so we can contact the new owner and you will not be contacted again regarding this recall.

# REIMBURSEMENT OF REPAIRS COMPLETED PRIOR TO THE RELEASE OF THIS RECALL

If you paid to repair your vehicle for this defect prior to receiving this recall letter, you may be eligible for reimbursement of the repair costs if they were incurred between 12/1/2004 and 12/31/2005. Contact your local International dealer, with your original repair documentation and proof of payment, and the service advisor will determine what if any of the repair costs will qualify for reimbursement. International dealers determine what repair costs are eligible for reimbursement. However, if you choose not to work through an International dealer, you may submit the enclosed "REQUEST FOR REIMBURSEMENT" form, repair documentation, and proof of payment to:

International Truck and Engine Corporation Warranty Claim Center Reimbursement Department P.O. Box 888 Warrenville, IL 60555

#### IF YOU NEED ASSISTANCE

If you take your vehicle to your International dealer on a mutually agreed upon service date, and the dealer does not remedy this condition without charge on that date or within five days, you can obtain assistance by following the procedure described in the Owner Assistance Guide section in your Owner's Manual or by calling toll free 1-800-448-7825.

You may also wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C., 20590, or call the toll-free Vehicle Safety Hot-Line at 1-888-327-4236 (TTY:1-800-424-9152): or go to <a href="http://www.safercar.gov">http://www.safercar.gov</a> if your International dealer fails to repair or is unable to remedy this condition without charge or within a reasonable time.

We request your prompt attention to the correction of this defect and apologize for any inconvenience this may cause you.

## INTERNATIONAL TRUCK AND ENGINE CORPORATION