

INTERNATIONAL TRUCK AND ENGINE CORPORATION 4201 WINFIELD ROAD, WARRENVILLE, IL 60555

TRUCK GROUP

SAFETY RECALL 06502

May 2006

Dear International Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. International® has decided that a defect which relates to motor vehicle safety exists in the **engine oil sampling system** of certain 9400*i* models built between 4/27/2005 and 1/23/2006 with feature code 12WEE - *ENGINE OIL SAMPLE VALVE Mounted on the Right Rail in the Front Wheel Well.* The vehicle identified on the enclosed card fits this description and our records show that you own this vehicle. Federal regulations require that any vehicle lessor receiving this Recall notice must forward a copy of this notice to the lessee within ten days.

REASON FOR THIS RECALL

The hose connecting the engine block to the frame mounted oil sampling valve is routed too close to the engine's turbocharger. Heat from the turbocharger may cause the hose to melt.

RISK TO MOTOR VEHICLE SAFETY

If melting of the hose occurs, engine oil could be sprayed upward onto the surface of the turbocharger housing possibly causing smoke or a **fire**. This may lead to **property damage**, **personal injury** or **death**.

ACTION YOU SHOULD TAKE

- 1. Our records show that you are the owner of the vehicle identified on the enclosed card. If you are not the owner, please read paragraph number 6.
- **2.** Please contact your local International dealer, with your recall card in hand, to schedule an appointment to have your vehicle repaired.
- 3. Dealers will have parts and instructions to repair your vehicle by 5/19/2006. The repair will be performed without charge to you and will take approximately one hour.
- 4. When your local International dealer performs the inspection/repair, they will submit a warranty claim; therefore, you **DO NOT** have to mail in the campaign card.

- **5.** If the vehicle cannot be corrected, please mark on the enclosed card under "CHECK ONE" the box which best describes why the vehicle can not be repaired, and return the postage-prepaid card to us.
- 6. In the event you do not own the vehicle described on the card, please complete the card, fill in the new customer name and address if known, and return it to us. This information will allow us to update our records so we can contact the new owner and you will not be contacted again regarding this recall.

IF YOU NEED ASSISTANCE

If you take your vehicle to your International dealer on a mutually agreed upon service date, and the dealer does not remedy this condition without charge on that date or within five days, you can obtain assistance by following the procedure described in the Owner Assistance Guide section in your Owner's Manual or by calling toll free 1-800-448-7825.

You may also wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C., 20590, or call the toll-free Vehicle Safety Hot-Line at 1-888-327-4236 (TTY:1-800-424-9152): or go to http://www.safercar.gov if your International dealer fails to repair or is unable to remedy this condition without charge or within a reasonable time.

We request your prompt attention to the correction of this defect and apologize for any inconvenience this may cause you.

INTERNATIONAL TRUCK AND ENGINE CORPORATION