

INTERNATIONAL TRUCK AND ENGINE CORPORATION

4201 WINFIELD ROAD, WARRENVILLE, IL 60555

.....

TRUCK GROUP

Authorized Field Change Reminder G-03906 October 2004



THIS IS AN ISIS ONLY NOTIFICATION.

There will be NO Dealer Mailing for this EXTENSION NOTICE and REMINDER.

Please refer to the dealer letter G-03906 for service instructions.

SUBJECT: 8600 Models with Cummins ISM 2002 Emission Engines built between August 1, 2002 and February 3, 2003

8600 Models with Cummins ISM 2002 Emission Engines, built between August 1, 2002 and February 3, 2003 require an inspection and may require replacement of the air cleaner hose clamp. Vehicles will also require an inspection for proper clearance between the charge air cooler pipe and the cold air side air cleaner pipe.

This letter is to inform you that *owners* of suspect vehicles who have not completed the AFC Service Procedure, have been sent a reminder to schedule an appointment to have the service performed.

We appreciate your patience and cooperation regarding this campaign and apologize for any inconvenience this may cause.

INTERNATIONAL TRUCK AND ENGINE CORPORATION

AFC G - 03906