Gagan S (गगन एस)

| C. | _ | ·~ | |
|----|---|----|--|

Vivek Dhiman (विवेक धीमान)

Sent:

13 June 2022 09:27

To: Cc: anandconstructions22@gmail.com; vedurla hariprasad

Sreedhar N (श्रीधर एन); P Vijay Kumar (पी विजय कुमार); Pandeeswaran Chinna Karuppiah (पंडीस्वरण चिन्ना करुपपीय); Gagan S (गगन एस)

Subject:

Reg: Safety Deviation during excavation works (Rain Water Harvesting Sump at Block B)

Dear Sir,

This mail has reference to the subject and our discussion held with your site Engineer earlier today.

Please note that, following safety deviation has been observed while carrying out the excavation works for Rain Water Sump at B.

Diesel filling was carried out while the Excavator was in Running condition.

In view of the same, a penalty of INR 500/- is imposed and you are advised to get your safety supervisor and Excavator Operator F&S Training regarding for ensuring safe operations of Machinery.

Details of Safety Personal: TAMANARA MANOJ

ESIC No. - 7011157923

Details of Excavator Operator:

ABDUL SALAUDDIN

ESIC No. - 2112699777

Safety Induction Training This is for information and immediate compliance please on 14/06/2022

Thanks and Regards Vivek

AC.-CISE

Picase Allow to dery induction Training

5n 3.66.227 me 13:00

विकि प्रबंधका - सूरका Sr. Manager-Security एड देश हो ति ति.ति.Inverva

डिक्सन, के.ए. DIXON. K.A. प्रबंधक - अग्निशमन व स्रक्षा Manager-Fire & Safety

To, MSN Multy

ple impart training

to above contractor

to above contractor

to above contractor

They were Sat an the class trul session.

and I Conselled Drives and

Sattlet Surporish on Machine.