

Repair Estimate

Authorised workshop: City Auto Care, Bengaluru (workshop sample)
Vehicle Registration: KA03PQ4455
Customer: Arjun Mehta

Front bumper	INR	42,000
Bonnet	INR	58,000
Radiator and condenser	INR	36,500
Headlamp assembly (pair)	INR	44,000
Airbag module and SRS	INR	38,000
Rear bumper repaint	INR	9,500
Labour	INR	12,000

TOTAL	INR	240,000