

# Accident Evidence - Inspection Photo Report

Surveyor photo log (workshop sample)

Vehicle Registration: KA01AB1234

Claim customer: Rahul Sharma

Photographs observed:

1. Rear bumper cracked and displaced.
2. Tailgate panel dented.
3. Left and right tail lamp assemblies broken.
4. Rear parking sensors damaged.