

Repair Estimate

Authorised workshop: City Auto Care, Bengaluru (workshop sample)
Vehicle Registration: KA01AB1234
Customer: Rahul Sharma

Rear bumper replacement	INR	38,500
Tailgate panel	INR	56,200
Tail lamp assembly (L and R)	INR	24,800
Parking sensors	INR	12,400
Paint and labour	INR	28,700
Alignment and miscellaneous	INR	11,800

TOTAL	INR	172,400