Minitab Project Report

1) Find a 95% confidence interval for the population mean time it takes to manufacture.

One-Sample T: Time

Variable	N	Mean	StDev	SE Mean	95%	CI
Time	25	48.00	10.30	2.06	(43.75,	52.25)