FAULT FORGE / TRAINING REPORT

A change in surface finish

Learner: Alex Morgan

Difficulty: Beginner

Session: 3fbcc051-6b67-4bc8-9282-65d5e357e2cf

Synthetic educational simulation; not a practical qualification.

Criterion	Recorded points
Diagnosis	50
Evidence	20
Quiz	30
Reasoning	Not required
Total	100

Diagnostic feedback

In this authored fixture, increased tool overhang and the controlled comparison support insufficient tooling stiffness. Vibration alone would not distinguish this from bearings or workholding.

Instructor feedback

No instructor review recorded.

Next exercise

Compare the strongest evidence with one plausible alternative before your next exercise.

Rubric

diagnostic-reasoning/1.0

Scenario SHA-256

1069a168b85043f805798709df8b6958de7b788597ec26e83129f1e1c0c3f445