Motor and Control Test Record

Assessment Record

Operator: Oak Terrace Veterinary Clinic LLC. Location: 1539 Alder Court, Suite D.

Claim CLM-26-876731; examination date 2026-08-29.

Condition and Repairability

The compressor and vacuum stand against the utility wall described in the maintenance ledger. Both have water entry and failed winding tests. The housings show dull deposits below the fresh water mark. There is no pre-incident service test for these units in the supplied file. The vendor has quoted matching replacement assemblies.

Test Record

Assembly	Observed test condition	Service route
Compressor	Water entry at motor/control assembly	Matching replacement assembly
Vacuum unit	Winding insulation failure after drying	Matching replacement assembly

Pricing Scope

This equipment examination records condition, repair route and asset identity. The subsequent vendor quotation contains the installation and disposal prices.