Plumbing Attendance Sheet

Service Record

Customer: Cedarline Medical Center LLC. Claim reference: CLM-26-402550.

Visit: 2026-08-15. Address: 1454 Alder Court, Suite D.

Cause Assessment

The threaded adaptor at the north-wing distribution header fractured below the pressure gauge. Water ran down the riser and crossed the transfer corridor before the overnight guard closed the main. The removed adaptor shows a fresh circumferential break. A pressure test of the remaining header did not identify a second active opening.

Work Notes

The service ticket was closed on 2026-08-15 after the connection test. The technician recorded work at the connection and the accessible immediate area. Finish reinstatement was not carried out under this ticket.