Scope and Price Comparison

Review Assignment

Cost file for Birchstone Dental Lab LLC, CLM-26-348735. Prepared by Cypress Independent Surveyors on 2026-09-08.

The bench reinstatement scope retains the working surfaces, drawer faces and tool rails. The comparison prices cover lower substrate replacement and the affected socket route, with access around the supported bench tops. The dry finishing end is excluded from the floor repair area.

The comparison uses current local trade prices for the described work. Lump-sum allowances include normal labor, materials, waste and access within each priced scope. Prices are in USD before tax.

Reviewed Line L1

Drywall replacement, water-damaged partitions

Submitted line: $15,250.00. Independently reviewed lump-sum allowance: $15,250.00.

The comparison includes the removal and reinstatement operations listed for this trade, within the marked work boundary.

Reviewed Line L2

Flooring (LVT) replacement

Submitted line: $22,800.00. Independently reviewed lump-sum allowance: $22,800.00.

Scope reference: Wash-up island and the associated removal/reinstatement boundaries in the survey.

Reviewed Line L3

Baseboard and paint

Submitted line: $8,800.00. Independently reviewed lump-sum allowance: $8,800.00.

The allowance follows the independent takeoff and local trade comparison recorded in this cost file.

Reviewed Line L4

Ceiling tile and grid

Submitted line: $7,200.00. Independently reviewed lump-sum allowance: $7,200.00.

The comparison includes the removal and reinstatement operations listed for this trade, within the marked work boundary.

Reviewed Line L5

Cabinetry / millwork repair

Submitted line: $13,100.00. Independently reviewed lump-sum allowance: $13,100.00.

Scope reference: Wash-up island and the associated removal/reinstatement boundaries in the survey.

Reviewed Line L6

Electrical receptacles and associated branch wiring

Submitted line: $4,400.00. Independently reviewed lump-sum allowance: $4,400.00.

The allowance follows the independent takeoff and local trade comparison recorded in this cost file.

Reviewed Line L7

Demolition and debris removal

Submitted line: $7,950.00. Independently reviewed lump-sum allowance: $7,950.00.

The comparison includes the removal and reinstatement operations listed for this trade, within the marked work boundary.

Reviewed invoice_01

Vendor charges on invoice_01: $12,950.00.

The independently accepted price is $12,950.00. The service descriptions and duration were compared with the vendor work record and local service pricing.

Reviewed invoice_02

Vendor charges on invoice_02: $21,100.00.

The independently accepted price is $21,100.00. The service descriptions and duration were compared with the vendor work record and local service pricing.

Reviewed Coordination

Accept 10% combined overhead and profit on the sum of the independently priced primary building repair lines. The separate service invoices already include their own crew management. The comparison base is the repair-trade scope described above.

Price Comparison Schedule

Line	Scope description	Submitted	Review opinion
L1	Drywall replacement, water-damaged partitions	$15,250.00	$15,250.00
L2	Flooring (LVT) replacement	$22,800.00	$22,800.00
L3	Baseboard and paint	$8,800.00	$8,800.00
L4	Ceiling tile and grid	$7,200.00	$7,200.00
L5	Cabinetry / millwork repair	$13,100.00	$13,100.00
L6	Electrical receptacles and associated branch wiring	$4,400.00	$4,400.00
L7	Demolition and debris removal	$7,950.00	$7,950.00