# Connection Repair Work Order

## Service Record

Customer: Birchstone Dental Lab LLC. Claim reference: CLM-26-348735.

Visit: 2026-08-25. Address: 1624 Alder Court, Suite D.

## Cause Assessment

A hot-water connector inside the wash-up island burst at a formed bend. The local isolation stopped the discharge. The plumber replaced the connector, ran hot water through the new connection and checked the surrounding couplings. The island waste trap was intact and was not the release source.

## Work Notes

The service ticket was closed on 2026-08-25 after the connection test. The technician recorded work at the connection and the accessible immediate area. Finish reinstatement was not carried out under this ticket.