Utility Plant Condition Sheet

Assessment Record

Operator: Harborview Diagnostics LLC. Location: 1471 Alder Court, Suite E.

Claim CLM-26-902082; examination date 2026-08-25.

Condition and Repairability

The diagnostic utility compressor and vacuum pump share a low cabinet beside the chase. Standing water entered the electrical housings. The specialist isolated and bench-tested both units; the test sheet records shorted winding circuits. Replacement modules include the same capacity and mounting dimensions as the installed units.

Test Record

Assembly	Observed test condition	Service route
Compressor	Water entry at motor/control assembly	Matching replacement assembly
Vacuum unit	Winding insulation failure after drying	Matching replacement assembly

Pricing Scope

This equipment examination records condition, repair route and asset identity. The subsequent vendor quotation contains the installation and disposal prices.