Motor and Control Test Record

Assessment Record

Operator: Rivermark Office Suites LLC. Location: 1437 Alder Court, Suite C.

Claim CLM-26-786122; examination date 2026-08-23.

Condition and Repairability

A portable compressor and central cleaning vacuum were standing in water at the base of the service riser. Bench testing found failed winding insulation in both. Their asset tags match the office operator's equipment schedule. The service shop lists complete replacement assemblies for these models; individual windings are no longer stocked.

Test Record

Assembly	Observed test condition	Service route
Compressor	Water entry at motor/control assembly	Matching replacement assembly
Vacuum unit	Winding insulation failure after drying	Matching replacement assembly

Pricing Scope

This equipment examination records condition, repair route and asset identity. The subsequent vendor quotation contains the installation and disposal prices.