Water Service Call Record

Service Record

Customer: Rivermark Office Suites LLC. Claim reference: CLM-26-786122.

Visit: 2026-08-14. Address: 1437 Alder Court, Suite C.

Cause Assessment

A coupling above the kitchenette ceiling discharged into the service riser. The building engineer had isolated the branch before arrival. A replacement coupling held pressure during a twenty-minute test. The plumber photographed the removed fitting but did not open the tenant partitions.

Work Notes

The service ticket was closed on 2026-08-14 after the connection test. The technician recorded work at the connection and the accessible immediate area. Finish reinstatement was not carried out under this ticket.