Utility Plant Condition Sheet

Assessment Record

Operator: Fernhollow Dental Group LLC. Location: 1420 Alder Court, Suite B.

Claim CLM-26-585247; examination date 2026-08-22.

Condition and Repairability

The compressor starter and the vacuum contactor sit at floor level in the utility closet. Water marks cross both housings. Insulation resistance remained below the manufacturer's minimum after drying. The motor assemblies are sealed and the quoted service parts omit the damaged winding packs. The labels and asset register identify both units as practice-owned.

Test Record

Assembly	Observed test condition	Service route
Compressor	Water entry at motor/control assembly	Matching replacement assembly
Vacuum unit	Winding insulation failure after drying	Matching replacement assembly

Pricing Scope

This equipment examination records condition, repair route and asset identity. The subsequent vendor quotation contains the installation and disposal prices.