Connection Repair Work Order

Service Record

Customer: Fernhollow Dental Group LLC. Claim reference: CLM-26-585247.

Visit: 2026-08-13. Address: 1420 Alder Court, Suite B.

Cause Assessment

A braided supply connector beneath the sterilization sink separated at its crimp. The technician found the isolation valve open and water striking the back of the cabinet. Closing that valve stopped the spray while pressure elsewhere in the suite remained stable. The removed connector was bagged and left with the practice manager.

Work Notes

The service ticket was closed on 2026-08-13 after the connection test. The technician recorded work at the connection and the accessible immediate area. Finish reinstatement was not carried out under this ticket.