Connection Repair Work Order

Service Record

Customer: Greenway Physical Therapy LLC. Claim reference: CLM-26-677883.

Visit: 2026-08-19. Address: 1522 Alder Court, Suite C.

Cause Assessment

The connector feeding the staff washbasin split behind the cupboard back. Water followed the plank joints from the cupboard into the exercise area. The plumber replaced the connector and left the basin isolated until a second pressure check later that day.

Work Notes

The service ticket was closed on 2026-08-19 after the connection test. The technician recorded work at the connection and the accessible immediate area. Finish reinstatement was not carried out under this ticket.