# Equipment Workshop Findings

## Assessment Record

Operator: Pine Ridge Pediatric Dentistry LLC. Location: 1505 Alder Court, Suite B.

Claim CLM-26-722023; examination date 2026-08-27.

## Condition and Repairability

The plant cupboard compressor and vacuum assembly have water entry at their lowest electrical openings. The service engineer recorded failed insulation tests after controlled drying. Replacement assemblies match the installed performance rating and connections. The practice's asset list contains both serial numbers.

## Test Record

| Assembly | Observed test condition | Service route |
|---|---|---|
| Compressor | Water entry at motor/control assembly | Matching replacement assembly |
| Vacuum unit | Winding insulation failure after drying | Matching replacement assembly |

## Pricing Scope

This equipment examination records condition, repair route and asset identity. The subsequent vendor quotation contains the installation and disposal prices.