Plumbing Attendance Sheet

Service Record

Customer: Northbend Imaging Center LLC. Claim reference: CLM-26-385027.

Visit: 2026-08-21. Address: 1556 Alder Court, Suite E.

Cause Assessment

A supply branch at the wash station opened above the control-passage ceiling. The operator isolated the floor supply before the equipment engineer arrived. The plumber replaced the failed connector and tested the branch with the access panel off. No water entry was found at the roof route above the room.

Work Notes

The service ticket was closed on 2026-08-21 after the connection test. The technician recorded work at the connection and the accessible immediate area. Finish reinstatement was not carried out under this ticket.